Mittagong Sands Pty Ltd

Cowra Quartz Quarry - Glen Logan Road, Cowra NSW 2794

EPA Licence No: 11420

Water Monitoring Requirements:

Grab sample weekly during any discharge.

Location of Monitoring Points:

Monitoring Point 4: South discharge point as indicated on figure 2.3 Site Layout - Southern Quarry site

map received on 17/12/2009.

Monitoring Point 5: North discharge point as indicated on figure 2.4 Site Layout - Northern Quarry site

map received 17/12/2009.

Summary of Results:

Pollutant	Unit of Measure	Lowest sample value	Highest sample value	Mean of samples
рН	рН	-	-	-
Total Suspended Solids	mg/L	-	-	-

Individual Results:

Monitoring Point 4:

Sample Date

Pollutant

Unit of Measure

No discharge events during period

Test Result

Monitoring Point 5:

Sample Date	Pollutant	Unit of Measure	Test Result		
No discharge events during period					

Mittagong Sands Pty Ltd

Cowra Quartz Quarry - Glen Logan Road, Cowra NSW 2794

EPA Licence No: 11420

Water Monitoring Requirements:

Grab sample weekly during any discharge.

Location of Monitoring Points:

Monitoring Point 4: South discharge point as indicated on figure 2.3 Site Layout - Southern Quarry site

map received on 17/12/2009.

Monitoring Point 5: North discharge point as indicated on figure 2.4 Site Layout - Northern Quarry site

map received 17/12/2009.

Summary of Results:

Pollutant	Unit of Measure	Lowest sample value	Highest sample value	Mean of samples
рН	рН	-	-	-
Total Suspended Solids	mg/L	-	-	-

Individual Results:

Monitoring Point 4:

Sample Date Pollutant Unit of Measure Test Result

No discharge events during period

Monitoring Point 5:

Sample Date

Pollutant

Unit of Measure

No discharge events during period

Mittagong Sands Pty Ltd

Cowra Quartz Quarry - Glen Logan Road, Cowra NSW 2794

EPA Licence No: 11420

Water Monitoring Requirements:

Grab sample weekly during any discharge.

Location of Monitoring Points:

Monitoring Point 4: South discharge point as indicated on figure 2.3 Site Layout - Southern Quarry site

map received on 17/12/2009.

Monitoring Point 5: North discharge point as indicated on figure 2.4 Site Layout - Northern Quarry site

map received 17/12/2009.

Summary of Results:

Pollutant	Unit of Measure	Lowest sample value	Highest sample value	Mean of samples
рН	рН	-	-	-
Total Suspended Solids	mg/L	-	-	-

Individual Results:

Monitoring Point 4:

Sample Date

Pollutant

Unit of Measure

No discharge events during period

Test Result

Monitoring Point 5:

Sample Date	Pollutant	Unit of Measure	Test Result		
No discharge events during period					